



UTTERMOST

ASSEMBLY INSTRUCTIONS

ITEM # : 21197

**IMPORTANT : TURN OFF THE POWER AT THE MAIN FUSE
OR CIRCUIT BREAKER BOX
BEFORE STARTING INSTALLATION**

Carefully unpack and identify all parts before assembly.

1. Threaded cap(I) onto nipple(J)
2. Install glass shade(D) on the part (E), put part(C) and counter rings(B) into the glass, then use the tool(A) to thread the counter rings (B) onto threaded sockets. .
3. Install stabilizer onto fitters by fastening counter rings onto threaded sockets.
4. Install metal cap(H) onto hex coupling(G) and fasten by the finial(F).
5. Install bulbs(not included). See label located at socket area for type bulb and maximum allowed wattage.
6. Locate the lower assembly upward and match the hooks onto the up and ends of support arms. Locate the ends of support arms onto the hooks inside arms.

