


Important: Label on back contains important information on your crystal color. Please save in case you ever need to order matching crystal.

Trim Diagram Vertex® Pendant VR0306A






Schonbek Worldwide Lighting Inc., 61 Industrial Blvd., Plattsburgh NY 12901-1908
Tel: 800.836.1892 or 518.563.7500 www.schonbek.com

© 2005 SCHONBEK WORLDWIDE LIGHTING INC., A. SCHONBEK & CO. LTD. WORLDWIDE COPYRIGHT RESERVED

US PATENT #D522,683, #D522,687, #7,101,065, #D532,144, #D560,027 & #7,347,594 / CANADIAN DESIGN ® #109752



Trim Diagram Vertex® Pendant VR0306A



1 Light 3 x 3 x 5½"

Geometrix[™] is designed by Schonbek with Swarovski Spectra[®] crystal.




This design is the proprietary trade dress/trademark of Schonbek Worldwide Lighting Inc.

Please save your trim diagram for future reference.

IMPORTANT: Label on back contains important information on your crystal. Please save in case you ever need to order matching crystal.





REPLACING CRYSTAL: If a crystal breaks, you'll see a bare pin sticking out of a hole in the framework. PIN 8001/14 850-207 A Straighten pin outward. **B** Slide crystal octagon and then bead onto pin. Bend back into frame to


secure crystal in place.

How to Install Xenon Bulb and Vertex® Pendant:


Pendants may be mounted to monorail systems, monopoints or line voltage track by coupling to the quick connect transformer adapter. Attached to the socket is a cable that may be cut on site during installation to any length (see instructions below).

- 1 Plug bulb carefully but completely into socket. Use a Xenon T3 G4 12V bulb.
- **2** Position the cross plate of the pendant against the socket and secure in place by screwing the crystal pyramid onto the socket until tight.
- **3** Attach crystal finial N1096 to bottom point of crystal pyramid by pinching the hanger together and inserting.


How to Shorten the Cable:




4 Cut the cable cleanly with wire cutter to desired length, and slide brass collar over wire. Position collar so that a small section (1/16") of braided wire protrudes from the top of the collar.



5 Grasping the collar, slide braided outer wire back to expose inner wire. Trim 1/8" of insulation from the inner wire with wire stripper.



6 Feed inner wire into quick connect adapter until it reaches top set screw. Feed braided outer wire and brass collar into quick connect.



7 Tighten top set screw first, then lower set screw snugly. Smooth out any bulges in braided wire.

8 Screw quick connect into quick connect adapter until it seats. If you adjust the orientation of the pendant, be careful not to loosen the connection.