# The Coppersmith

## Copper Pier Mount Installation Instructions

Refer to the Gas and Electric lantern installation instruction provided with the lantern.
This installation should be performed by a licensed professional.

1. Attach the CPM base to the mounting surface using fasteners that are suited for the mounting surface.
   (Fasteners for step 1 are not included)

CPM

BASE

Mounting Surface

2. Install the straight flare fitting onto the bottom of the lantern. (Provided)

3. Fasten the CPM onto the bottom of the lantern. (fasteners included)

Note: For Electric Lantern installations, refer to the lantern Installation instructions and make electrical connections accordingly.

4. Using 1/4" soft copper tubing, make a coil and attach a 1/4" flare nut as shown.

1/4" Flare Nut

Coiled copper tubing

5. Fasten the 1/4" flare nut onto the straight fitting.

6. Slide the CPM down onto the base. Using the fasteners provided. Connect CPM onto the base.

IMPORTANT NOTE
Leak testing should be conducted Before the CPM is connected to the Base.

For additional technical assistance, Contact The CopperSmith @ 1-866-249-1918 thecoppersmith.net
Thank you for choosing CopperSmith products.