UVING ISTRICT

Collection: Mel

Installation manual for: LD6004W5C W5" H15.5" E5" L1

Installation instructions:

1. Black wire from ceiling(junction box) attaches to "L"wire from the fixture.

2. White wire from ceiling(junction box) attaches to "N"wire from the fixture.

- 3. "E" wire from the fixture is attaced to the mounting bracket and an additional "E" wire from the mounting bracket must be secured to the junction box.
- 4.Secure mounting bracket to the junction box.


5.Insert the mounting bracket screw(P2) into the mounting bracket (P1)

6.Put the canopy(P3) on the mounting bracket(P1)and use the screw(P4)to screw tighten.

7.Install E12 light source, no include bulb.

8.Install the shade(P9)to the bullb.

The end!



PARTS LIST

Part Number	Part	Picture	Description	Qty
MB6R43	P1	•	mounting bracket D4.3″	1
	Ρ2	ammin))	Mounting bracket screw	2
	Ρ3		Canopy D4.7"	1
P-LD6004W5C-1	Ρ4	I	Screw	3
	Ρ5	$\langle\!\!\langle$	UL18#, L6″	1
	P6		Lamp Arm	1
	Ρ7	Ê Î	E12 holder	1
	P8		D0.87"*L2.1" Candle cover	1
FS6R01WH	Р9		D3.5″*H7.5″ Lamp shade	1

"L" = Hot wire "N" = Neutral wire "E" = Ground wire