



Remarks:

L =line,

3 =high speed, 2=medium speed, 1=low speed,

O=on/off ⊗=light



Motor wiring sketch

