


ASSEMBLY INSTRUCTIONS FOR #30543 / PN5-PP2856-05



IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEFORE STARTING INSTALLATION

CAREFULLY UNPACK AND IDENTIFY ALL PARTS BEFORE ASSEMBLY. BULBS ARE NOT INCLUDED.

1.) REMOVE CAP AND FINIAL FROM BOTTOM OF FIXTURE. NIPPLE AND CROSSBAR CAN BE REMOVED FOR INSTALLATION.

2.) ATTACH CROSS BAR TO JBOX USING SCREWS.

3.) ATTACH ALL WHITE CORDS TOGETHER AND WIRE TO POSITIVE LINE. ADD A WIRE CRIMP, NOW ATTACH ALL BLACK CORDS AND RUN THEM UP TO NEGATIVE CORD AND CRIMP. FINALLY ATTACH COPPER WIRE TO GROUND AND CRIMP TOGETHER.

4.) PUSH UP FIXTURE UP TO JBOX, MAKING SURE NOT TO CRIMP CORDS. PUT BOTTOM CAP BACK ON AND SCREW FINIAL ON BOTTOM OF NIPPLE GOING THROUGH FIXTURE TO HOLD IN PLACE AND SECURE.



"A Commitment to Excellence in Lighting and Service"

CALL OUR CUSTOMER SERVICE DEPARTMENT AT 1-800-222-4009
 MONDAY - FRIDAY 8:00a.m - 6:00p.m ET
 visit us on the web at www.meyda.com