

Item # F847L-HBZ/MP

Product Family Name: Timber Category: INTERIOR FAN Certification 4000048 Patents: UPC Code: 706411059766 Finish: Heirloom Bronze with Maple Blades Category Type: Ceiling Fan



Notes:



Blade Finish: Blade Material: HAND CARVED Blade Sweep: 84" Downrod 1: 10	No. of Blades: 3 Downrod 1 Outsid Dia: .75	24 DEGREES de Downroad 2:	Downrod 2 Outside Dia:
Ceiling to Lowest Point: (Dim A) 15.5	Ceiling to Blade (Dim B) 17.25	Lead Wire: 80	Motor Size: 172 x 25mm
RPM: Amps: Watts: CFM: CFM/Watts:	Low Low/M 33 0.08 4.85 3475.0 716.49	led. Medium M	Ned/High High 75 0.53 35.87 8794.0 245.16



/!`

Pull Chain Control:Works with Remote Control: Works with Wall Control:NoYesYesReversible:Included Remote Control:Included Wall Control:YesRC600Preside Control:Preside Control:

Image File Name: F847L-HBZ/MP.jpg

LAMPING


No. of Bulbs: 1 Max Bulb Wattage: 26	Light Type: Z26 LED Socket: Y22 LED MO	Light Kit Optior	nal: No	
Integrated Light Kit: Yes		Ballast:	Rated Life Hours: 30000	Uplight: No
Bulb/LED Included: Yes	Color Temp.: 3000	CRI: 94	Initial Lumens: 2227.0	Delivered Lumens: 1305.7

GLASS

Description: ETCHED WHITE Part No.:		Material: PC LENS Quantity: 1
Width:	Height:	Length:
8.5	0.75	8.5

SHIPPING

Carton Width: 14.63	Carton Height: 11.0	Carton Length: 44.13
Carton Weight:	Carton Cubic Feet:	Small Package Shippable:
25.56	4.11	Yes
	Maatan Daali Ulainkti	Maatan Daalul an othu



WARNING: Handling this product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. Wash hands with soap and water after installing, handling, cleaning or otherwise touching this product. For more information go to: www.P65Warnings.ca.gov.

For additional information, please contact Customer Care: 1-800-221-7977 | Product depicted on this spec sheet is protected by United States Federal and/or State laws including US Patent, Trademark and/or Copyright and unfair competition laws. Unauthorized reproduction or use carries severe legal penalties.

Rev 10.25.2021 11:03 AM