INSTALLATION INSTRUCTION H / L / J Track Systems Quick Connect[™] adapter

EN-HO50AR, EN-LO50AR, EN-JO50AR

WAC LIGHTING

Responsible Lighting[®]

Read all instructions before installing. Switch off power before installing.

OVERVIEW:

Transformers are designed for use on WAC 120V H, L or J series track. They accept WAC Quick Connect™ fixtures and pendants. They may also be used on other manufacturers' brand of track (consult factory for compatibility). Transformers are electronic type, and may generally be dimmed with standard incandescent dimmers.


EN-HO50AR (H Track): Rated 12 volt, 50-watt max. EN-LQ50AR (L Track) : Rated 12 volt, 50-watt max. EN-JQ50AR (J Track) : Rated 12 volt, 50-watt max.

INSTALLING THE QUICK CONNECT:

- 1. Place the metal decorative ring over the threads of the "QC" adapter.
- 2. Insert the male quick connect into the quick connect adapter.
- 3. Thread the top half of the conical section until it seats with the adapter.
- 4. Adjust fixture position; use caution not to loosen the conical section.

FIXTURE INSTALLATION

- 1. Note the track head contacts, and the polarity groove running the length of the track.
- The two contacts should be positioned so that when rotated, they will face the grooved side 2. of the track (this is the side with two flat copper wires running its length).
- 3. Insert adapter into track slot. Rotate the adapter 90°.
- 4. Center the locking tab until it sits in the track slot.
- 5. Removal is the reverse procedure. Adapters may be positioned anywhere along the track length.



Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050

Western Distribution Center 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585

WAC Lighting retains the right to modify the design of our products at any time as part of the company's continuous improvement program. JULY, 2014

