INSTALLATION INSTRUCTIONS

American Standard

Style That Works Better

Porcelain Enameled Steel Bathtubs

0255.102 New Salem Bathtub, RHO 0255.202 New Salem Bathtub, LHO

0263.102 New Solar AFR Bathtub, RHO 0263.202 New Solar AFR Bathtub, LHO

A CAUTION: THIS NEW FIXTURE HAS A DURABLE FINISH; HOWEVER, EXTRA CARE SHOULD BE EXERCISED DURING INSTALLATION WHEN ROUGH HANDLING AND THE DANGER OF DROPPED TOOLS MAY CAUSE DAMAGE.

_		1000				7
1	Check the tub thoroughly for shipping damage, report any apparent damage to the location that furnished the tub and request their advice on continuing with the installation.	2	Protect this bathtub during installation and construction by using this corrugated container as indicated. Cut along the dotted lines and place the corrugated protector over the top and front of the tub. The center cut-out drops into the center of the tub.	3	After measuring the dimensions of the product, frame the construction area.	U R E U S E
4	Locate the tub in position and mark a joist so that a 2x4 stringer can be nailed in place. The stringer will be located under the flange against the wall. Nail in place the 2x4 support. Re-position the tub and check for level, both front to back and left to right.	5	It may be necessary to shim the tub to achieve a good level condition. Only small shims should be used in conjunction with the bathtub's own support pad. Note: There will be a small gap between the apron panel and the floor to allow for tile, carpeting, etc. Caulking could be used to seal this gap.	6	Overflow and drain assembly, faucet and the shower head should be installed to the manufacturers specifications. Over-tightening the drain can damage the tub.	EFORFUT
	CARE AND CLEANING Clean with warm water, a soft cloth and mild detergent. Never use abrasive scouring powders, cleansers or pads.		STRINGER			N A S

AMERICAN STANDARD ONE-YEAR LIMITED WARRANTY

If inspection of this American Standard plumbing product, within one year after its initial installation, confirms that it is defective in materials or workmanship, American Standard will repair or, at its option, exchange the product for a similar model.

This warranty **does not apply** to local building code compliance. Since local building codes vary considerably, the purchaser of this product should check with a local building or plumbing contractor to insure local code compliance before installation.

This warranty **shall be void** if the product has been moved from its initial place of installation; if it has been subjected to faulty maintenance, abuse, misuse, accident or other damage; if it was not installed in accordance with American Standard's instructions; or if it has been modified in a manner inconsistent with the product as shipped by American Standard.

American Standard's option to repair or exchange the product under this warranty does not cover any labor or other costs of removal or installation, nor shall American Standard be responsible for any other incidental or consequential damages attributable to a product defect or to the repair or exchange of a defective product, all of which are expressly excluded from this warranty. (Some states or provinces do not allow the exclusion or limitation of implied warranties, so this exclusion may not apply to you.)

This warranty gives you specific legal rights. You may have other statutory rights that vary from state to state or from province to province, in which case this warranty does not affect such statutory rights.

For service under this warranty, it is suggested that a claim be made through the contractor or dealer from or through whom the product was purchased, or that a service request (including a description of the product model and of the defect) be sent to the following address:

In the United States: American Standard Brands P.O. Box 6820 Piscataway, New Jersey 08855 Attention: Director of Consumer Affairs

For residents of the United States, warranty information may also be obtained by calling the following toll free number: (800) 442-1902 www.americanstandard-us.com In Canada: AS Canada ULC 5900 Avebury Ave. Mississauga, Ontario Canada L5R 3M3 Toll Free: (800) 387-0369 www.americanstandard.ca In Mexico: Customer Service Manager AS Maquila, S.A. de C.V. Via Morelos #330 Col. Santa Clara Ecatepec 55540 Edo. Mexico www.americanstandard.com.mx