

3890-10 GB

01



3890-M1L GB

NOTE: Assemble the bottom finial after you hang the fixture.

CSA021103HALG1

## INSTALLATION INSTRUCTION CH-1

For Chandelier Light Fixtures (Rev.07-02-07)

OFF AT FUSE OR CIRCUIT

## HANGING THE FIXTURE (Fig.1)

WARNING! SHUT POWER

- Shut off the power at the circuit breaker and remove old fixture from ceiling, including the old crossbar
- Carefully unpack new fixture and lay all the parts on a clear surface.
- Thread nipple (C) into loop (F) until snug
- into crossbar (D) until snug. Thread other end of nipple (C) with loop attached
- Place lock washer (B) over of nipple protruding through crossbar and thread hex nuts (A) onto nipple until tight.
- 6 Take this crossbar assembly and mount to ceiling screw securely with screwdriver. junction box with junction box screws (E). Tighten
- Use a pair of pliers to open one end link of the chair provided, and connect to the fixture loop (J). Close
- ,∞ disconnect and discard remaining chain. needed for proper hanging height. Using pliers By measuring, determine correct number of links
- Lace the fixture wires through the chain
- 10. Slip loop collar (H) over the chain, then do the same with the canopy (G)
- 11. Open the other end link of the chain and hang the 12. Feed the fixture wires through the loop (F), and fixture on the loop at the ceiling. Close the link

## CONNECTING THE WIRES (Fig.2)

nipple (C) and pull until taut.

- Take the black wire from the ceiling junction box and the smooth wire leg from the fixture and twist of wires until snug. bare ends together. Twist wire connector onto end
- If your junction box has a grounding wire (green or Repeat same process with white junction box wire you twist the wire connector onto wires. NOTE: Twist wires together in the same direction and ribbed wire of fixture.
- Tuck these wire connections neatly into the ceiling to the ceiling. Raise the loop collar (H) and thread junction box has no ground wire, attach the bare bare copper), attach this wire and the bare copper wire from the fixture together as in step 13. If onto ceiling loop protruding through canopy outlet box and then raise the canopy (G) all the way copper fixture wire to the junction box with a screw
- fixtures specifications.

  NOTE: DO NOT EXCEED THE SPECIFIED

Install the light bulbs in accordance with the

to the junction box & test the fixture. Your installation is now complete. Turn power on at





