





Patent Pending Assembly Instruction For 53860




Surface Mount Installation

Step One




Using hands, separate outer aluminum shell from LED lamp

Step Two



Using included hardware and a screw driver, secure outer aluminum shell to cabinet surface


Step Three



Feed connecting cord through a pre-drilled hole in the cabinet surface or through the cut-out of the outer aluminum shell. Secure LED lamp into outer aluminum shell.


Recessed Installation

Step One




Using hands, separate outer aluminum shell from LED lamp

Step Two



Cut out from the bottom of the cabinet a hole using a 2.5" hole saw.

Step Three



Feed connecting cord through the hole in cabinet and secure LED lamp.