

UTTERMOST LIGHTING ASSEMBLY INSTRUCTIONS

ITEM# : 21050

**IMPORTANT : TURN OFF THE POWER AT THE MAIN FUSE
OR CIRCUIT BREAKER BOX
BEFORE STARTING INSTALLATION**

Carefully unpack and identify all parts before assembly.

1. Install glass shade onto fitters and Install candles onto glass by fastening counter rings onto threaded sockets
2. Screw nipple into hex coupling.
3. Install fixture assembly onto fitters by ball finial.
4. Install bulbs (no included). See relamping label located at socket area for type and maximum allowed wattage.

