


INSTALLATION AND WIRING DIAGRAM

USA

LEDRA® SERIES LEDS

LEDRA® 32

ART. NO.	135 361al	aluminum, white	135 371al	dome, aluminum, white
	135 361al-l	aluminum, warm white	135 371al-l	dome, aluminum, warm white
	135 362al	aluminum, blue	135 372al	dome, aluminum, blue
	135 363al	aluminum, green	135 373al	dome, aluminum, green
	135 364al	aluminum, red	135 374al	dome, aluminum, red
	135 365al	aluminum, amber	135 375al	dome, aluminum, amber



IMPORTANT SAFETY INSTRUCTIONS



1. THIS PRODUCT MUST BE INSTALLED BY A PERSON FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT AND THE HAZARDS INVOLVED, IN ACCORDANCE WITH LOCAL NEC CODE.
2. WET LOCATION SUITABLE.
3. SUITABLE FOR SUSPENDED CEILING.
4. FOR WET LOCATION INSTALLATION, FIXTURE MUST BE SURFACE MOUNTED OVER A RECESSED JUNCTION BOX (MAX DIAMETER 3 1/2")
5. WHEN MOUNTING ONTO UNEVEN SURFACES, SILICONE MUST BE APPLIED IN BETWEEN THE CANOPY HOUSING AND THE SURFACE TO PREVENT WATER INFILTRATION.
6. Turn off power prior to any work on the systems.
7. Warranty is void in case of unauthorized modifications and/ or improper use.

READ ALL OF THESE INSTALLATION INSTRUCTIONS BEFORE INSTALLING THE FIXTURE

Contents of Delivery:

LEDRA® 32 - qty. (1)

Note: Fixture must be mounted over a standard junction box

- Begin by connecting the feed wire (A) through gasket (G) from the transformer to the power cables in the wall.

- Insert the mounting screw (C) into the mounting plate (B).

- Align the mounting screws (C) through gasket with the J-box and tighten until firmly connected.

- Connect male and female quick connect (F) then place the LEDRA® 32 (D) over the mounting plate (B) and secure with the allen screws (E) located on the side of the base.

