

Upload/Download PC Data	* 4 5 8 *
Print Clock Settings	* 4 5 7 *
Print User Code List	* 4 5 6 *
Print Audit Trail	* 4 5 5 *
Timed Passage Mode	* 4 7 4 7 * [] [] [] [] XXX Hours

Quick Function List



DL & PDL5300 Quick-Reference Guide to Programming Codes and Functions

This is only a summary of Programming Codes and Functions. Refer to Programming instructions W11622 & W11672 for more information. **01351 6/08**

Quick Function List

Entering Program Mode	[_ _ _ _ _]	Master Code
Change Master	[_ _ _ _ _] [_ _ _ _ _]	New Master Code Confirm New Master Code
Add/Delete User	[_ _] [_ _ _ _ _]	User Number New User Code
Disable User	[_ _]	User Number
Enable User	[_ _]	User Number
<i>Fold on Line</i>		
Set Date	[_ _ _ _ _]	Date, MM DD YY
Set Time	[_ _ _ _]	Time, HH MM 24 Hour Format
Set Day	[_]	Day (1 – 7), Sun =1
Enable Passage Mode		
Disable Passage Mode		
Exit Program Mode	Hold down any key for 5 seconds	