




RZ-T1X

Cove / Cabinet / Showcase / Display
LED Surface Mount Series


INSTALLATION INSTRUCTIONS

Please read and save these instructions. Read carefully before using product. Failure to comply with instructions could result in personal injury and/or damage to product or property. Please retain instruction sheet for future reference.

TOOLS REQUIRED



PHILLIPS SCREWDRIVER




HAMMER

HARDWARE INCLUDED



2X MOUNTING SCREWS



14X WIRE CLIP

1

REMOVE LED MODULES FROM TRACK, SECURE TRACK ON MOUNTING SURFACE WITH INCLUDED MOUNTING SCREWS.

2

MOUNT LED MODULES ON TO TRACK. MAKE SURE EACH MAKES GOOD CONTACT WITH THE TRACK.

3

AFTER ALL THE LED MODULES ARE MOUNTED, PLUG IN POWER FEED CABLE INTO TRACK'S POWER INPUT.
Note: If cable plugged into the other end the track the dimmer/on-off switch will not work

USE PROVIDE WIRE CLIPS TO SECURE CORD ON SURFACE WITH A HAMMER. CAREFUL NOT TO DAMAGE THE CORD.
(Recommended to place a wire clip every 5 inches)

INSTALLING POWER SUPPLY BEHIND MOUNTING SURFACE

MEASURE 1-3/4" AWAY FROM POWER ENDCAP, DRILL A 3/8" HOLE. THREAD THE POWER CONNECTOR THROUGH THE HOLE AND CONNECT TO POWER ENDCAP. USE WIRE CLIP IF NECESSARY TO ORGANIZE CORD BEHIND MOUNTING SURFACE.

4

PLUG IN POWER SUPPLY (24W) INTO A POLARIZED OUTLET.

5

PRESS BUTTON ON POWER ENDCAP TO TURN ON THE FIXTURE. PRESS AND HOLD THE POWER BUTTON TO DIM EACH LED PUCK HEAD.