


ASSEMBLY INSTRUCTIONS FOR #61797-1-PB (133794)



IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEFORE STARTING INSTALLATION

CAREFULLY UNPACK AND IDENTIFY ALL PARTS BEFORE ASSEMBLY. BULBS ARE NOT INCLUDED

THIS FIXTURE WEIGHS OVER 50 LBS. NEC:314.27B, A luminaire that weighs more than 23kg (50lb) shall be supported independently of the outlet box unless the outlet box is listed AND MARKED for the MAXIMUM weight to be supported.

THIS IS A TWO PERSON JOB

- 1.) Feed fixture wires through bottles and bushings as shown.
- 2.) Place fixture wires up through canopy and determine each individual overall height from ceiling to bottom of bottles.
- 3.) Add 1" to pre-determined fixture wire length and place strain relief clip onto wire at this location.

(Leave enough wire to gather in center of canopy and attach to j-box)

- 4.) Using needle nose pliers, crimp strain relief clip onto fixture wire as shown.
- 5.) Consolidate all the loose fixture wires using wire nuts. (Utilize pigtail method)
- 6.) One person, carefully raise up canopy with all bottles attached while second person wires fixture to j-box per local electrical code.

- 7.) Mount canopy to a secure location with customer supplied lag bolts.



"A Commitment to Excellence in Lighting and Service"

CALL OUR CUSTOMER SERVICE DEPARTMENT AT 1-800-222-4009

MONDAY - FRIDAY 8:00 a.m. - 6:00 p.m. ET

visit us on the web at www.meyda.com