


### Illustrated Parts

Handshower w/Wall Bracket & Hose		
MODEL	<b>TYPE</b>	<u>FINISH</u>
3861EP	Wand	Chrome
3861EPBN	Wand	Brushed Nickel
3861EPORB	Wand	Oil Rubbed Bronze
3861EPNL	Wand	Nickel
3861EPWR	Wand	Wrought Iron
DISCONTINUED		
3861	Wand	Chrome
3861BB	Wand	Brushed Bronze
3861PW	Wand	Pewter
3861BN	Wand	Brushed Nickel
3861WR	Wand	Wrought Iron
3861AN	Wand	Antique Nickel
3861ORB	Wand	Oil Rubbed Bronze
3861NL	Wand	Nickel
3861AZ	Wand	Antique Bronze
3861P	Wand	Polished Brass
3861CP	Wand	Chrome/Pol. Brass





#### **■** Order by Part Number


There is more than 1 version of this model. Page down to identify the version you have.

- <u>2nd generation</u> valve manufactured on and after September 3rd, 2009. Can be identified by the check stop nut (smaller drive feature).
- 147208 Thermostatic cartridge will not work in 1st generation valves.

## **Illustrated Parts**

ExactTemp® 3/4" Thermostatic Valve

**MODEL** S3371





#### ■ Order by Part Number


- 1st generation valve manufactured prior to September 3rd, 2009. Can be identified by the check stop nut.
- 130156 Thermostatic cartridge will not work in 2nd generation valves.

## **Illustrated Parts**

ExactTemp® 3/4" Thermostatic Valve

**MODEL** 

S3371





### Order by Part Number

Rev. 10/09

There is more than 1 version of this model. Page down to identify the version you have.


- <u>2nd generation</u> valve manufactured on and after July 27th, 2009. Can be identified by mounting plate and smaller drive feature (1-1/8") on adapter nut.
- 147210 volume control cartridge will not work with 1st generation valves.

### **Illustrated Parts**

ExactTemp® 3/4" Volume Control Flow Valve

MODEL S3600

#### 2nd Generation Valve Parts



TO ORDER PARTS CALL: 1-800-BUY-MOEN

www.moen.com



#### ■ Order by Part Number


- 1st generation valves manufactured prior to July 27th, 2009. Valves can be identified by a lack of a mounting bracket and drive feature on adapter nut (requires open ended wrench).
- 130157 volume control cartridge will not work with 2nd generation valves.

## **Illustrated Parts**

ExactTemp® 3/4" Volume Control Flow Valve

MODEL S3600

### 1st Generation Valve Parts



TO ORDER PARTS CALL: 1-800-BUY-MOEN www.moen.com

Rev. 10/09



### Illustrated Parts


#### Order by Part Number

TS3116pt: Rev. 3/11

Trim can be used with \$3371 3/4" Thermostatic & \$3600 Volume Control valves

#### WATERHILL™ ExacTemp® 3/4" Thermostatic Tub/Shower Trim

**SHOWER TRIM ONLY VALVE TRIM ONLY FINISH** TS3110 TS3112 Chrome TS3110BN **Brushed Nickel** TS3112BN **TS3110WR TS3112WR** Wrought Iron **TS3110NL** Nickel **TS3112NL** Oil Rubbed Bronze TS3110ORB **TS3112ORB** 



TO ORDER PARTS CALL: 1-800-BUY-MOEN www.moen.com



# **Replacement Parts**



#### Waterhill™

ExactTemp® 3/4" Thermostatic Vertical Spa Trim

Models: TS516 Chrome

TS516BN Brushed Nickel TS516ORB Oil Rubbed Bronze

TS516NL Nickel

TS516WR Wrought Iron

Order by Part Number for use with S936 3/4" Thermostatic & S956 Volume Control valves

