
Standard Table Assembly Instructions

- .) Place table upside down on a cratch free surface (A).
- .) LOOSELY attach legs with upplied bolts (B).
- .) If applicable, **LOOSELY** attach ring(s) b legs with provided bolts (C).
- .) Without moving table from assembly osition, gently test stability of table legs.



.) Begin to gently tighten all nuts or bolts in succession, never torque ne bolt completely as this could make the table wobble. Instead, tighten ach bolt slightly, then move to the next in succession until all bolts are ecurely fastened.

lote: Extruded Aluminum may give and bend, so slight, but firm pressure an be applied during assembly, with caution.

Varning: Do not force components and over tighten the nuts during assembly.

