Gambit 7-Light Chandelier



GENERAL PRODUCT INFORMATION:

This product is suitable for damp locations.


These fixtures are intended to be installed utilizing NEC compliant junction boxes.




This product can be dimmed with a LED or TRIAC dimmer. Consult lamp manufacturer for additional information.

This instruction shows a typical installation.


Preparing the Canopy



1 Remove the crossbar from the canopy by completely unscrewing the center strain relief.




2 Mount the crossbar assembly to the electrical box with the two provided #8-32 screws.



CAUTION - RISK OF FIRE


This product must be installed in accordance with the applicable installation code by a person familiar with the construction and operation of the product and the hazards involved.

Use minimum 90°c supply conductors.




Loosen (**Do Not Remove**) the set screw on each strain relief.

Install the Fixture




1 Feed a fixture cord through each the strain relief.


Note: Taping down the frayed end of the cloth may assist in feeding it through the strain relief.



- 2 Adjust each fixtures' height (from bottom of the fixture shade to top of the canopy) by pulling the fixture cords through the strain relief.
- When the desired look is achieved, tighten the set screw on each strain relief.




- 4 Leave 6" of the cord behind the canopy for power connections. Cut the excess cord.
- 5 From the end of the cord, strip the insulation 4" using a sharp knife. Make sure not to nick the inner wires.
- 6 Strip the end of the wires.
- 7 Repeat for all the cords.



- 8 Leave the center cord for now and connect half of the fixture wires with the white tracer as well as one of the provided white wire strips together with one of the provided wire nuts.
- Repeat for the remaining half of the fixture wires with the white tracers except for the center cord.
- Connect neutral power line, the center cord power wire with white tracer, and the two white strips from the previous connection with one of the provided wire nuts.
- Repeat steps 8, 9, and 10 for the hot power cord wires and the neutral power cord wires with the green tracer.
- Ground the fixture wires and the mounting plate ground wire with accordance to local electrical code.


Install the Canopy



NOTE: It is recommended that one person hold the fixture while the electrician finishes the installation.

- Place all wires and wire nut connections properly inside the canopy.
- 2 While supporting the fixture, loosen the set screw on the center strain relief.
- Align the canopy center hole with the crossbar center hole.
- 4 Slide the canopy up against the ceiling and secure it in place by tightening the center strain relief into the crossbar. Do not turn the cord.
- Reposition the height of the center fixture if necessary and tighten the plastic set screw to secure the cord.


Install the Lamp and Shade



CAUTION: To reduce the risk of a burn or electric shock during relamping, disconnect the power to the fixture.

Refer to fixture marking for lamp information

1 Screw the lamp into the socket.



CAUTION: DO NOT OVER TIGHTEN the glass. This may break the glass resulting in injury.

2 Gently screw the glass onto it's base.

SAVE THESE INSTRUCTIONS!



7400 Linder Ave, Skokie, IL 60077 847.410.4400

www.techlighting.com

© 2017 Tech Lighting, L.L.C. All rights reserved. The "Tech Lighting" graphic is a registered trademark of Tech Lighting, L.L.C. Tech Lighting reserves the right to change specifications for product improvements without notification.

A Generation Brands Company